

















T-Box guide

1	 <div style="border: 1px solid black; padding: 5px; width: fit-content; float: right;">Handbook # 34335</div>
2	<div style="border: 1px solid black; padding: 5px; display: inline-block;">MAX 10N.m</div> 
3	 <div style="border: 1px solid black; padding: 5px; display: inline-block; margin-left: 100px;">TD1</div> 
4	 <div style="display: inline-block; margin-left: 20px;">3h 20m</div>  
5	  
6	
7	 
8	 

For more details read T-Box handbook.

QUICK START

To just measure torque follow the **RED** bold path.



TDMS guide

